

N. M. GIL CONC. COMMISSION  
UNITED STATES  
P. O. BOX 1930  
DEPARTMENT OF THE INTERIOR  
HOBBS, NEW MEXICO 88240  
GEOLOGICAL SURVEY

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other ☐
2. NAME OF OPERATOR  
The Superior Oil Company
3. ADDRESS OF OPERATOR  
P. O. Box 3901 Midland, Texas 79702
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 1980' FNL, 660' FEL, Section 22  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH: Same
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:

- |                      |                          |                          |
|----------------------|--------------------------|--------------------------|
| TEST WATER SHUT-OFF  | <input type="checkbox"/> | <input type="checkbox"/> |
| FRACTURE TREAT       | <input type="checkbox"/> | <input type="checkbox"/> |
| SHOOT OR ACIDIZE     | <input type="checkbox"/> | <input type="checkbox"/> |
| REPAIR WELL          | <input type="checkbox"/> | <input type="checkbox"/> |
| PULL OR ALTER CASING | <input type="checkbox"/> | <input type="checkbox"/> |
| MULTIPLE COMPLETE    | <input type="checkbox"/> | <input type="checkbox"/> |
| CHANGE ZONES         | <input type="checkbox"/> | <input type="checkbox"/> |
| ABANDON*             | <input type="checkbox"/> | <input type="checkbox"/> |
| (other)              | Weekly Drilling Report   |                          |

5. LEASE  
NM-16354
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME  
Paducah Federal Com
9. WELL NO.  
1
10. FIELD OR WILDCAT NAME  
Wildcat
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec. 22, T25S, R32E
12. COUNTY OR PARISH  
Lea County
13. STATE  
New Mexico
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)  
3408.6 GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

RECEIVED  
SEP 18 1982

OIL & GAS  
U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

8-28-82 Drlg to 12,870'.  
8-29-82 Drlg to 13,018'.  
8-30-82 Svy @ 13,054=1°. Drlg to 13,054'. Dropped Totco. Slugged DP. POH.  
8-31-82 TIH. Washed 80' to btm. No fill. Drlg to 13,076'.  
9-1-82 Drlg to 13,109'. Circ.  
9-2-82 POH for Bit #14. TIH. Drlg to 13,136'.  
9-3-82 Drlg to 13,194'.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED G. E. Tate TITLE Prod. Supt. DATE 9-7-82

ACCEPTED FOR RECORD (This space for Federal or State office use)  
(ORIG. SGD.) DAVID R. GLASS  
APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

OCT 8 1982

U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO

\*See Instructions on Reverse Side

RECEIVED

OCT 13 1982

O.C.D.  
HOBBS OFFICE