

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. Division
P.O. Box 1380
Hobbs, NM 88241

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT --" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well: ☒ OIL WELL ☐ GAS WELL ☐ OTHER

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address and Telephone No. 205 E. Bender, HOBBS, NM 88240 397-0405

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
Unit Letter C : 455 Feet From The NORTH Line and 1980 Feet From The
WEST Line Section 15 Township 25S Range 32E

5. Lease Designation and Serial No.
LC 062300

6. If Indian, Alottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and Number
COTTON DRAW UNIT
75

9. API Well No.
30-025-27873

10. Field and Pool, Exploratory Area
PADUCA DELAWARE

11. County or Parish, State
LEA, NEW MEXICO

12. Check Appropriate Box(s) To Indicate Nature of Notice, Report, or Other Data

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Attering Casing
☒ OTHER: EXTENSION OF TA STATUS
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Texaco Exploration and Production Inc. requests an extension of one year of the Temporarily Abandonment Status of the above well which ended on 5/23/99. The original Temporary Abandonment Status was approved on 7/27/95 based upon the results of a casing integrity test conducted on 5/23/95. This well was originally TA'D on 5/23/95 with a CIBP set @ 4620' and capped with 35' cement, (PBDT @ 4585'). The casing and plug were successfully tested to 520 psi for 30 minutes. TEPI requests TA status on this well through 5/23/01. A copy of the 5/23/95 chart is on back. Justification: A \$2,400,000 Cotton Draw 3D seismic acquisition was completed in late 1995. Texaco is processing the 3D survey. Texaco would like to hold the deeper Cotton Draw wells in idle/TA status until the seismic data can be completely analyzed.

(INTERNAL TEPI STATUS REMAINS TR-O)

TA APPROVED FOR 12 MONTH PERIOD
ENDING 5-23-2000


14. I hereby certify that the foregoing is true and correct.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 6/24/99
TYPE OR PRINT NAME J. Denise Leake

(This space for Federal or State office use)
APPROVED BY (ORIG. SGD.) GARY GOURLEY TITLE PETROLEUM ENGINEER DATE JUL 07 1999

CONDITIONS OF APPROVAL, IF ANY:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



Date: 5/23/95
Well Name: Cohen Draw Unit #75
Supervisor: Ray Short
Performers: 4686 - 4728'

