N. M. O'' CONS. COMMISSION P. O. BU., 1980

į

HOBBS, NEW MEXICO 88240

ROSWELL, NEW MEXICO

Form 9-331

.

.

Perm 9–331 Dec. 1973	Form Approved. Budget Bureau No. 42-R1424
UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	NM-45706
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use form 9-331-C for such proposals.)	7. UNIT AGREEMENT NAME
1. oil gas X other	8. FARM OR LEASE NAME Federal DD
2. NAME OF OPERATOR	9. WELL NO.
Amoco Production Company 3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME Talco Strawn
 P. O. Box 68, Hobbs, New Mexico 88240 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
AT SURFACE: 660' FSL X 1980' FEL AT TOP PROD. INTERVAL: (Unit 0, SW/4, SE/4) AT TOTAL DEPTH:	34-25-35 12. COUNTY OR PARISH 13. STATE Lea NM
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE	14. API NO.
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF	
REPAIR WELL APR	1 9N983 Report results of multiple completion or zone change on Form 9-330.)
CHANGE ZONES	& GAS
(other) status update ROSWELL	IOMT. SERVICE NEW MEXICO
 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertinent. Shut-in for 42 hr with closed casing pressure Released packer and circulated bottoms up. Pl tool, seal assembly, and 2-7/8" tailpipe. Repipe, 2-1/16" string reamer, 1-5/8" drillpipe Tagged fill at 13,073'. Wash to 13,290' and ran Gamma Ray CCL from 14,200'- to 12,200'. If and 2-7/8" CS Hydrill tubing. Packer set at 12,984'. Pressure test packer to 2000 psi-0K with wireline and perf Strawn intervals 14,166 14124'-28', 14080'-84', 14008'-16', 13994'-98 48', 13820'-24', 13792'-96' and 13,766'-72' wirecovered 6 BLW. Well began to flow and flower 30-35' flare. Flowed 6 more hrs. with light resubstrates baker Valve: MHNU! and Type. J. Nash, HOU 1-CMI. 18. I hereby perify that the foregoing is true and correct such as the foregoing is true and correct. 	Nectionally offlied, give subsurface locations and it to this work.)* O PSI and tubing pressure O PSI. OH with 2-7/8" tubing, on-off an 2-1/8" bit, 1 jt. 1-5/8" drill , and 2-3/8 and 2-7/8" tubing. clean out to 14,217'. POH and Ran 2-7/8" ABC Modified tubing 12,088' and tailpipe landed at . Ran 1-1/16" tubing perf gun 5'-14,168', 14,174'-76', 14138'-42 ', 13984'-90', 13970'-76', 13845'- ith 2 JSPF. Swabbed 1/2 hr. and ed 4 hours. Recovered 80 blw with nist water and 30-35' flare. Move 4
APPROVED BY	ACCEPTED FOR RECORD
CONDITIONS OF APPROVAL, IF ANY:	JUIL 5 1983
*See Instructions on Reverse S	Stule

out service unit 4-6-83 and began installing surface equipment to test well. Started flow test 4-10-83. Flow test 3 days. Last 17 hr recovered 140 BC, 0 BW, and 2,400 MMCFD. Choke plugged with rubber. Shut-in and repaired choke. Currently, shut-in waiting on service unit

RECEIVED JUL 7 1983 O.C.D. HOBRS OFFICE

· 这些人的,我们的**会的你**没有这些。

,

•

a Barra and a state of the state of the