

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☐ other Dry

2. NAME OF OPERATOR

Maralo, Inc.

3. ADDRESS OF OPERATOR

P. O. Box 832, Midland, Texas 79702 0832

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 330/N & 2310/W

AT SURFACE:

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☐
☐
☒

RECEIVED
JAN 5 1983

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

OIL & GAS
MINERALS MGMT. SERVICE
ROSWELL, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12-28-82 Called USGS for plugging data. Spotted 50 sx Class "C" Neat cmt. Plug TD to 3742'. Spotted 50 sx Class "C" Neat cmt w/2% CaCl₂. Plug 3365' to 3212'. Spotted 50 sx Class "C" Neat cement w/2% CaCl₂ - 250' to 2350'. Spotted 80 sx. Class "C" Neat cmt. w/2% CaCl₂ - plug 1550' to 1376'. WOC 4 hrs. Tagged plug @ 1475'. Spotted 20 sx cmt plug at surface. All cement plugs were witnessed by Mr. Dillow from USGS.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Brenda Colman TITLE Agent DATE 12-29-82

(This space for Federal or State office use)

(Orig. Sgd.) PETER W. CHESTER

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL OCT 31 1983