

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIP
(Other instructions
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC-067968

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL GAS WELL OTHER

7. UNIT AGREEMENT NAME

WDQSU

2. NAME OF OPERATOR
Sirgo-Collier, Inc.

8. FARM OR LEASE NAME

West Sallardside Green
and 717

3. ADDRESS OF OPERATOR
P.O. Box 3531, Midland, TX 79702

9. WELL NO.

30-72

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

10. FIELD AND POOL, OR WILDCAT

WDQSU Sallardside Green

Unit P, 150 FSL, 150 FEL, Sec. 30, T24S, R38E

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 30, T24S, R38E

14. PERMIT NO. 236

15. ELEVATIONS (Show whether DF, WT, GR, etc.)
3155' GR

12. COUNTY OR PARISH
Lea

13. STATE
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)

PULL OR ALTER CASING
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other) Spud, Cmt. surf, Prod.

REPAIRING WELL
ALTERING CASING
ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

* Spud well on 6-27-87 with 12 1/2" bit.

6-27-87* Ran 419' 24# 8-5/8" surface casing.

* Cemented w/250 sx. Class "C" 2% CaCl₂ (Circ. to surface),

* Test csg. to 500# for 1.5 hrs.

6-28-87* Drilled 7-7/8" hole to total depth of 3867'.

6-29-87* Ran 3867' of 5 1/2" 15.5# csg.

* Cemented w/1100 sx. of cement (Circulated to surface)

* Ran 13 centralizers.

RECEIVED

ACCEPTED FOR RECORD

SJS
JUL 29 1987

LEA COUNTY, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED Trinity D. Collier

TITLE Agent

DATE 7/24/87

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side