

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-30877
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	LC-067968
7. Lease Name or Unit Agreement Name	WEST DOLLARHIDE-DRINKARD UNIT
8. Well No.	98
9. Pool Name or Wildcat	DOLLARHIDE TUBB DRINKARD
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3180' KB

SUNDRY NOTICES AND REPORTS ON WELL  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>I</u> <u>2546</u> Feet From The <u>SOUTH</u> Line and <u>161</u> Feet From The <u>EAST</u> Line Section <u>30</u> Township <u>24S</u> Range <u>38E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3180' KB

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐  
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-20-98: MIRU. PULL RDS & PMP. INSTL BOP. TAG FILL.

1-21-98: WELLCHECK 2 7/8" TBG OUT OF HOLE. TIH W/BIT & BAILER ON TBG. C/O FILL FR 6882-6900'. (PBDT).

1-22-98: RAN SONIC HAMMER TOOL ON TBG. WSHD DRINKARD PERFS 6542-6682 & UPPER ABO PERFS 6751-6870' W/54 BFW. ACIDIZED DRINKARD & ABO PERFS W/5000 GALS 15% NEFE THRU SONIC HAMMER. FLSH W/10 BFW.

1-23-98: RAN SEAT NIPPLE, TBG, & TUBING ANCHOR. REM BOP. LAND SEAT NIPPLE @ 6872'. PMP 70 BBLS WTR DN CSG & 30 BBLS WTR DOWN TBG TO FLUSH ACID RESIDUE.

1-24-98: RAN GAS ANCHOR ON PMP. LOAD TBG W/15 BW. PRESS TEST TBG TO 500 PSI-OK. RD PULLING UNIT. ON PROD @ 2:30 PM.

1-30-98: PMPD 2 DRUMS TECHN-HIB 793 MIXED IN 20 BW. FLSH W/250 BW.

2-01-98: ON PRODUCTION @ 9:00 AM. PMPNG & TESTING.

2-3-98: ON 24 HR OPT. PMPD 63 BO, 100 BW, & 18 MCFD. STATUS IS PUMPING.

FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 2/4/98

TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use)

APPROVED BY ORIGINAL SIGNED BY CHRIS WILLIAMS TITLE DISTRICT I SUPERVISOR DATE 2/4/98

CONDITIONS OF APPROVAL, IF ANY: