SUNDRY NOTICES AND REPORTS ON Do not use this form for proposals to drill or to deepen or reentry	
	LC-032715
Use "APPLICATION FOR PERMIT" for such p	
SUBMIT IN TRIPLICATE	7. If Unit or CA, Agreement Designation
1. Type of Well: OIL GAS WELL WELL OTHER	8. Well Name and Number COOPER JAL UNIT
2. Name of Operator TEXACO EXPLORATION & PRODUCTION II	NC. 402
3. Address and Telephone No. 205 E. Bender, HOBBS, NM 88240	397-0419 9. API Well No.
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	
Unit Letter L2150 Feet From The S Line and 50	10. Field and Pool, Exploaratory Area Feet From The LANGLIE MATTIX 7 RVRS Q GRAYBURG
W Line Section <u>19</u> Township <u>24S</u>	11. County or Parish, State         Range37E         LEA ,
12. Check Appropriate Box(s) To Indicate	Nature of Notice, Report, or Other Data
TYPE OF SUBMISSION	
	Jonment Change of Plans
	npletion New Construction
	ng Back I Non-Routine Fracturing
	g Repair Water Shut-Off ng Casing Conversion to Injection
Final Abandonment Notice	
	(Note Report results of multiple completion on Well Completion or Recompletion Report and Log Form.)
<ol> <li>Describe Proposed or Completed Operations (Clearly state all pertinent detai work. If well is directionally drilled, give subsurface locations and measured</li> </ol>	
11/11/97 MIRU Dawson Production Services. Pulled 90k and tbg would not Day 1 11/12/97 Tih w/overshot and catch tbg. Ran freepoint and found tbg anchor severe rod wear. Picked up overshot, bumper sub, 6 3 ½" dc's. SION	
11/13/97 Picked up 87 its 2 7/8 its and caught fish. Jarred on fish and could 11/14/97 Poh w/tbg, and fish assy. Tih w/4 ¾ shoe and 1 it of washpipe, jar foam unit. SION	s and dc's. Could not gain circulation. Ordered air foam unit and rigged up air
Wireline set CIBP at 3400 and capped w/35' of cmt(new PBTD 3365'). Til v ND bop and flanged up well. SION	cked up 4 ¾ bit and scraper and tih to 3660. Pooh and laydown tools. By Rotary v/new 2 7/8 production tbg. TAC at 2914, SN at 3290, Bottom of tbg at 3322.
11/18/97 Tih w/new pump w/12' gas anchor, 7-1 ½" Kbars(replaced all cplg: rods. Hang on and load and test. Rig down Dawson. 1/8/97 FINAL OPT TEST 24 Bls. oil 333 Bls. water 11 MCF gas	s), replaced 41 $\%$ " rods and cpigs, ran total of 42 $\%$ " rods, 44 7/8" rods, 36 1"
- <b>N</b>	
14. Thereby certify that the foregoing is true and correct	
	gineering Assistant DATE 1/8/98
TYPE OR PRINT NAME Mike Quintana	
(This space for Federal or State office use)	
APPROVED BYTITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:	