LOCATION 1270' FSL, 137	70' FWL, Sec	c. 5, T25S, R3	7E, Lea Co. NM	
OPERATOR Kenson Operation				
DRILLING CONTRACTOR Unit	ted Drillin	g, Inc.		
		۰.		•
The undersigned here of the drilling contracto ducted deviation tests ar	or who dril	led the above (described well	representative and had con-
Degrees @ Depth	Degrees	s @ Depth	Deg	rees @ Depth
3/4° @ 514'			<u>. ——</u>	
1° @ 994'				
1° @ 1512'				
1° @ 2059'				
1° @ 2569'				
3/4° @ 2993'				
1° @ 3800'				
			ω	
				T
	Drilli	ng Contractor_	United Drillin	
		Ву:		George Aho
		Title:_	Business Manag	ger
Subscribed and sworn to l	before me t	his <u>3rd</u> day	of <u>December</u>	·
20 <u>01</u> •		<i>A</i> .	1	
20 <u>01</u> •		$\left(\frac{1}{2}\right)$	Mutine (

