

\* = please attach pertinent documents

V. PRODUCTION / BRINE STORAGE (continued)

Brine storage facilities (describe) BRINE PIT CONSTRUCTED WITH 30 MIL BLACK  
HYPALON 6X6 SCRIM WITH A FINISHED BLANKET 155'X155'=24,025 SQ. FT.

Current condition/status of brine storage pit EXCELLENT

Is brine storage pit currently being monitored for leakage? YES

Specify company or agency which is monitoring leakage \_\_\_\_\_

NEW MEXICO STATE ENGINEER

If pit leakage has been monitored in past use note to explain. \_\_\_\_\_

Comments on production history (note if production rates or brine \_\_\_\_\_  
concentrations have changed through time) NO CHANGE FROM INITIAL INSTALLATION