

(SUBMIT IN TRIPLICATE)

Land Office **Las Cruces**Lease No. **063965**Unit **Phillips**UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

HODGE OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 1, 1949

Well No. 1 is located 330 ft. from S line and 660 ft. from E line of sec. 24
33/4 Sec. 24 24S 36E N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Langlie-Mattix Lea New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

8 5/8" 32# casing set at 249' and cemented by Halliburton on 11/29/49 with 100 sax regular cement, plus 50 sax Incor and 100 lbs. calcium chloride. Cement circulated to surface. Well let set 48 hours and drill plug 12/1/49, and test with 500# pump pressure.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company CULBERTSON & IRWIN, INC.Address Box 1071, Midland, Texas

By

Title President