

Budget Bureau 48-238.2
Approval expires 12-31-66

			I

(SUBMIT IN TRIPLICATE)

**UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**

Land Office Santa Fe
 Lease No. MM- 6241
 Unit P

RECEIVED
OCT 6 1954

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASINGS.....	X
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	X
NOTICE OF INTENTION TO PULL OR ALTER CASINGS.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....	X		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

CITIZEN SERVICE JOURNAL

July 13, 1954

Well No. 2 is located 660 ft. from S line and 660 ft. from E line of sec. 35

22/4 35 24 B. 26 B 1007H
 (S. and S. No.) (Page) (Page) (Page) (Location)

~~Page No.~~ _____
(Date)

~~No.~~ _____
(County or Subdivision)

Name, Rank and Grade of Officer

The elevation of the ~~structure~~ ^{ground} above sea level is 32.99 ft.

no wall sign on
Bldg #2 this morning

DETAILS OF WORK

(State names of and expected depths to objective sands; show size, weights, and lengths of proposed casings; indicate casing jobs, cementing points, and all other important proposed work)

145° - 13-2/8" Rm., Matted and Pulled after 8-5/8" Rm. 2 heavy
780° - 10-2/8" Rm., Matted and Pulled after 8-5/8" Rm.
1240° - 8-5/8" Rm., Covered with 590 sacks.
3770° - 7" Rm., Covered with 190 sacks, out at 2415° and pulled.

Location OK

Flagged as follows: 50 sacks on bottom; 100 sacks at 2400'; cement plug in top of 8-5/8" and 4-1/2" pipe cemented in 1/2 of Steel Drum which was set over and directly on top of 8-5/8" casing and collar was then filled in around and on top of cemented drum. Collar and pits have been completely leveled and filled.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company L.L. Mack

Admission _____ Date 174

Midland, Texas

B.

10