NEW MEX. JOIL CONSERV SANTA FE, NEW		iON Rev	Form C-110 vised 7/1/55
File the original and 4 copies with the	appropriate di	strict offic	:e)
CERTIFICATE OF COMPLIANC TO TRANSPORT OIL AND			
Company or Operator Jal 011 Company, Inc.		Lease <u>ja</u> t	NM = 324
Well No. 2 Unit Letter H S 35 T 2	SR 36 E Pool	Jalmat	
County Lea Kind of Lease (S	state, Fed. or 1	Patented)_	Patented
If well produces oil or condensate, give locatio	n of tanks:Unit	A S 35	T 94 S 1 36 E
Authorized Transporter of Oil or Condensate	-		Contrany G
Address Midland, Texas (Give address to which approved co	ny of this form	is to be s	enth "
			entre T
	mal Gas Co.		- <u>w</u>
Address <u>Box 1384</u> Jal, New Give address to which approved co	<u>Mexico</u>	is to be s	$\frac{1}{2}$
If Gas is not being sold, give reasons and also			
• •			
El Paso Natural Gas Co. has been no	tifled for hook	up or gas	
	· · · · · · · · · · · · · · · · ·		
Reasons for Filing: Please check proper box)	New Well		(<u>*</u>)
Change in Transporter of (Check One): Oil ()	Dry Gas ()(C'head ()	Condensate ()
Change in Ownership ()	Other		
Remarks:	Other \Give	explanation explanation	on below)
Well made .47 bbls. load oil per hour \neq 7 i We expect the well to make oil due to cond	bbls. water per ltions existing	hour on mil in Satkins	L ti-point test e # 1.
The undersigned certifies that the Rules and Remission have been complied with.	egulations of the	e Oil Conse	ervation Com-
Executed this the 25 th ay of August 19	58		
	Ву	11:00, 1	Inter
Approved19	Titlengi		

OIL CONSERVATION COMMISSION

Title '

Company Jal 011 Company, Inc.

Address Drawer Z

Jal, New Mexico

JAL OIL COMPANY, INC.

P. O. BOK 1744 LEGGETT BUILDING MIDLAND. TEXAS

September 4, 1958

Mr. Randy Montgomery New Mexico Oil Conservation Commission P.O. Box 2045 Hobbs, New Mexico

> Re: Jal Oil Co., Inc. Natkins # 2 Unit H, Sec. 35-24S-36E Lea County, New Mexico

Dear Sir:

This will confirm our telephone conversation of August 15, 1958, concerning testing the above well. As agreed, the well was tested thru the El Paso Natural Gas Company meter at watkins # 1 well in Unit $\approx -35-24-36$. The chart was removed and a new chart was used for testing # 2. When the test was completed the chart used for the test was taken off and labeled as gas from # 2 watkins. The number 1 well was shut in during the test.

El Paso Natural Gas Company has been notified of the completion and have staked the necessary right-of-way.

The well was tested thru the existing facilities at well $\frac{\pi}{\pi}$ 1 for conservation reasons.

Yours truly, Jal Oil Company, Inc.

imay Watson Dewey Jatson

Engineer

DW:bw