

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces
Lease No. 032618
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Midland, Texas, December 21, 1945

Well No. I.B.Ogg(a) #6 is located 660 ft. from [N] line and 1980 ft. from [E] line of sec. 35
SE 1/4 Sec. 35 24-S 36-E N.M. P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Cooper Lea New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3275 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Please refer to our "Notice of Intention to Abandon Well" filed with your office under date of 2-6-45. Plugging contractor moved in 11-1-45 and well was salvaged, plugged and abandoned as follows. A 65 sack cement plug was spotted in the 7" casing from from 3265' to 2940'. The 7" casing was parted and pulled at 1710' and a 30 sack cement plug spotted from 1720' to approximately 1650' (in top of parted 7" and in bottom of 9-5/8" Casing). The required 4" pipe marker was cemented in top of hole with 15 sacks leaving all 12-1/2" and 9-5/8" casing cemented in the hole. Hole was filled with heavy mud between above cement plugs. Above work was completed 11-7-45, and the location is now cleaned up and ready for inspection.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The Texas Company

Address Box 1270

Midland, Texas

By [Signature]

Title Drlg & Prod. Foreman