



(SUBMIT IN TRIPPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY



and Office Los Angeles
Lease No. 16 038150 (b)
Date May 17 1954



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	Subsequent Report of Sand Free	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 13, 1954

Well No. 3 is located 2900 ft. from SW line and 440 ft. from EW line of sec. 4

NE 1/4 of NE 1/4 of Sec. 4 (1/4 Sec. and Sec. No.) T-24-S (Twp.) R-37-E (Range) 107N (Meridian)

Langley-Walton (Field) Los (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 3699 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

In order to increase production the following work was done and results obtained:

Well was sand-flooded with 10,000 gallons oil mixed with 1/2 sand per gallon. Sealed in and tested. On 24 hour test flowed 6 BO and no water on 20/64" choke. Production prior to workover 2 BOFD.

ILLEGIBLE

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Stanolind Oil and Gas Company

Address Box 48

Los Alamos, New Mexico

By Kennell J. Sear

Title Field Engineer

1944

1944

1944

1944

1944

1944

1944

1944

1944

1944

1944

1944

1944

1944

1944

1944