

Getty Oil Company
No. 181 Myers Langlie Mattix Unit
SW $\frac{1}{4}$ SW $\frac{1}{4}$ sec. 4, T. 24 S., R. 37 E.
Lea County, New Mexico

U. S. Geological Survey
P. O. Box 1157
Hobbs, New Mexico 88240

HOBBS DISTRICT

CONDITIONS OF APPROVAL:

1. The Hobbs office (telephone (505) 393-3612) is to be notified when workover operations are to be commenced.
2. Blowout prevention equipment is required.
3. An injection profile survey is required when fill-up is obtained and surface injection pressure becomes necessary. A copy of the survey, together with your analysis, must be furnished this office. All steps necessary to ensure that the injected water enters only the proposed injection interval must be timely taken.
4. The surface injection pressure at the wellhead is not to exceed 900 psi unless it can be established that a higher pressure will not result in fracturing of confining strata and such higher pressure is approved.
5. Surface restoration is to be in accordance with the operator - land owner agreement.