



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Budget Bureau  
Approval expires 12-

Land Office **Las Cruces**

Lease No. **LC 032450(6)**

Unit **Courtland Myers**

Permit

US-313

REC-120

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		
<b>Subsequent Report on Change of Location</b>		<input checked="" type="checkbox"/>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

*Myers* July 10, 1954  
Well No. **1** is located **1980** ft. from **NW** line and **1980** ft. from **E** line of sec. **6**  
**NWSE** **6** **24S** **37E** **N.M.P.M.**  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
**Langlin-Mattix** **Lee** **New Mexico**  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled well on above location to 374' TD. Ran 365' 10 3/4", 32.5# csg. Cemented with 250 sxs at 365'. Drilled plug & shoe. After shoe drilled, pulled bit up in pipe and hung up. Attempted to go back to 374' & could not go below 367'. Either shoe is off in hole or bottom joint came loose. Cemented hole with 50 sxs. Permission granted by phone 9:30 A.M. 7-10-54 by USGS to do following: Skid 10' South making new location of 1970' from South Line and 1980' from East Line of Section 6, 24S, 37 E N.M.P.M. It was agreed to leave well number the same.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **R. OLSEN OIL COMPANY**

Address **Box 691**

**Jal, New Mexico**

By

**DEWEY WATSON**

Title **Geological Engineer**