

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

COPIES RECEIVED		
CONTRIBUTION		
FEE		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator Texas Pacific Oil Company, Inc.		8. Farm or Lease Name Hodge	
3. Address of Operator P.O. Box 4067, Midland, Texas 79701		9. Well No. 2	
4. Location of Well UNIT LETTER B 2310 FEET FROM THE East LINE AND 330 FEET FROM THE North LINE, SECTION 8 TOWNSHIP 24-S RANGE 37-E NMPM.		10. Field and Pool, or Wildcat Jalmat Gas	
15. Elevation (Show whether DF, RT, GR, etc.) 3286' G. L.		12. County Lea	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER Run Casing Survey <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER Completed <input type="checkbox"/>
OTHER OCCNM <input type="checkbox"/>			

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Surface - 8 5/8" - 24# Smls. set @ 281' w/200 sx. cmt.

0-PSIG

Oil String- 5 1/2" 15.5# Smls. set @ 2821' w/200 sx. cmt.

120 PSIG.

Tubing - 90 PSIG.

Dig out cellar-connected valve to surface to take pressure survey by OCC.

Completed 3-29-77 and Inspected by Melvin Crossland w/OCC.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *[Signature]*

TITLE **West District Oper. Supt.**

DATE **3-29-77**

APPROVED BY *[Signature]*

TITLE

DATE **APR 11 1977**

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

APR 10 1977

Oil Control Unit

Room 1111