1-JDM-Engrace -1-BWI-MLMU

0 0 10-WIO's 1-88 −

Form Approved. Budget Bureau No. 42-R1424

UNITED STATES DEDARTMENT OF THE INTERIOR

5. LEASE

	DEFARTMENT OF THE INTERIOR	NM-0321613
	GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
•		
S	UNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do no	ot use this form for proposals to drill or to deepen or plug back to a different oir. Use Form 9–331–C for such proposals.)	Myers Langlie Mattix Unit
		8. FARM OR LEASE NAME
1. 0	oil gas vell 🖟 weil 🗆 other	Myers Langlie Mattix Unit
	NAME OF OPERATOR	9. WELL NO.
	etty Oil Company	215
	ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME
P.O. Box 730, Hobbs, NM 88240 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17		Langlie Mattix
		11. SEC., T., R., M., OR BLK. AND SURVEY OR
т. L	elow.)	AREA
Α	T SURFACE: Unit Ltr. F, 1980' FNL & 1980' FWL	Sec. 8, 24S, 37E
A	I TOP PROD. INTERVAL:	Tal. STATE
Α	T TOTAL DEPTH:	TIEW TRATEO
16. C	HECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO.
R	EPORT, OR OTHER DATA	15 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5
		15. ELEVATIONS (SHOW DF, KDB, AND WD)
	EST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
	WATER SHUT-OFF	
	TURE TREAT	
	R WELL \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
	OR ALTER CASING	(NOTE: Report results of multiple completion or zone
MULT	IPLE COMPLETE	change on Form 9-330.)
	GE ZONES HOSS, NEW V	40000
ABANI	DON*	
(omer_) Cleaned out, placed well back on productio	on ကို ကိုင်္ချာမှ ရေး ကိုင်္ချာမှု မြို့ မြို့ မြို့
17. D	ESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly and	
in	ESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state coluding estimated date of starting any proposed work. If well is discussed and true vertical depths for all markets and zones portions.	e all pertinent details, and give pertinent dates,
m	neasured and true vertical depths for all markers and zones pertinen	it to this work.)*
/ 76	MIRU pulling unit Installed pop pulled	
	MIRU pulling unit. Installed BOP. Pulled bit and tagged fill @ 3495'. Drilled and c	out of hole with tubing. Ran 6 1/4
		and the second s
76	Ran 104 jts. (3526.66') 2 7/8" OD 6.4# tubi	ng and got 0 25511 gains
		ing and set & 3331. Set pump &
76	Placed well back on production.	
		그는 그는 그는 그는 것들만 수백 이 나는 것입券 앞
	1	

Subsurface Safety Valve: Manu. and Type	Set @	अपूर्वप	Fŧ
18. I hereby certify that the foregoing is true and correct			
SIGNED	4/1/81		
(This space for Federal or State office use)		r 	

APPROVED BY _______CONDITIONS OF APPROVAL, IF ANY:

DATE __

*See Instructions on Reverse Side

ACCEPTED FOR RECORD

U.S. GECLOGICAL SURVEY ROSWELL, NEW MEXICO