

**DUPLICATE**

NEW MEXICO OIL CONSERVATION COMMISSION  
Santa Fe, New Mexico

**RECEIVED**  
APR 29 1940  
**RECEIVED**

**MISCELLANEOUS REPORTS ON WELL**

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within **HOBBS OFFICE** after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut-offs, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below:

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	<b>X</b>
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL			

**Hobbs, New Mexico**

**April 26, 1940**

OIL CONSERVATION COMMISSION,  
Santa Fe, New Mexico.

Place

Date

Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the

**Repollo Oil Company**

**Fowler Hair**

Well No. **1** in the

COMPANY OR OPERATOR

LEASE

**NW** of Sec. **9**, T. **24S**, R. **37E**, N. M. P. M.,

**Mattix**

Field,

**Lea**

County

The dates of this work were as follows: **3/30/40**

Notice of intention to do the work was (was not) submitted on Form C-102 on \_\_\_\_\_ 19\_\_\_\_ and approval of the proposed plan was (was not) obtained. (Cross out incorrect words)

**DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED**

**Moved in clean out tools 3/30/40- TD 3575**

**This well was completed June 26, 1937 for 580Bbl. first 24 hour after shot w/ 200 quarts. Production declined to 18 barrels per day recently.**

**Well was not cleaned out after shot.**

**Propose to cleanout to bottom to increase production.**

**Went in hole with tools and found top of savings @ 3475' and continued cleaning-out until April 21st. Cleaning out to 3470.**

**Well flowed 80 barrels in 24 hours after cleaning out**

Witnessed by \_\_\_\_\_

Name

Company

Title

Subscribed and sworn to before me this **26th**

day of **April**

19**40**

*[Signature]*

Notary Public

I hereby swear or affirm that the information given above is true and correct.

Name

*[Signature]*

Position

**Dist. Supt.**

Representing

**Repollo Oil Company**

Company or Operator

My Commission expires

**2-4-42**

Address

**Hobbs, N.M.**

Remarks:

*[Signature]*  
**OIL & GAS INSPECTOR**

Title

