

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 032339 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Myers Langlie Mattix Unit

9. WELL NO.

227

10. FIELD AND POOL, OR WILDCAT

Langlie Mattix

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 10-24S-37E

12. COUNTY OR PARISH 13. STATE

Lea

N.M.

1. OIL ☒ GAS ☐
WELL WELL OTHER

2. NAME OF OPERATOR

Getty Oil Company

3. ADDRESS OF OPERATOR

P.O. Box 730 Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1980' FSL and 1980' FEL, Sec. 10

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3251 DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

PULL OR ALTER CASING

<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

REPAIRING WELL

<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other) Clean out & Deepen

<input checked="" type="checkbox"/>

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Pulled tubing and packer. Ran 6 1/4" Varel Tricone bit, reversed out to original TD and drilled new hole (40') to 3571', new TD. Runco treated open hole 3210' to 3571' with 1500 gals 15% NE acid and 2000# rock salt. Ran 2 3/8" 4.7# J-55 tubing and set at 3525'. Ran rods and pump, and put well on production 6-30-77.

18. I hereby certify that the foregoing is true and correct

SIGNED

Walter J. Carls

TITLE

Area Superintendent

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

DATE

12-14-77

ACCEPTED FOR RECORD

DATE

JAN 4 1978

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

1942
JAN 12
1942
JAN 12
1942
JAN 12

RECEIVED FOR RECORD
JAN 12 1942
U.S. DEPT. OF JUSTICE
FEDERAL BUREAU OF INVESTIGATION