Form 9-331 (May 1963)	DEPARTN	UNITED STATES MENT F THE INTERI FEOLOGICAL SURVEY	SUBMIT IN TRIPLICA (Other instructions c verse side)	5. LEASE DESIGNATION LC-032339	AU NO. 42-R1424.	
		CES AND REPORTS ( als to drill or to deepen or plug b TION FOR PERMIT—" for such pr		6. IF INDIAN, ALLOTTE	5 OF TRIBE NAME	
	AS VELL OTHER	Avers Langlie	7- UNIT AGREEMENT NAME Myers Langlie-Mattix Unit 8- FARM OR LEASE NAME			
Skelly Oil Company 3. ADDRESS OF OPERATOR 9. WELL NO. 1976 Myers Langlie-Mattix Unit 9. WELL NO.						
P. O. Box 4. LOCATION OF W See also space At surface	1351, Midland ELL (Report location cl 17 below.)	l, Texas 79701 learly and in accordance with any	State requirements OLOGICA	MEXICO Langlie-Matt	r wildcat İx	
Unit Letto	11. SEC., T., R., M., OR J SURVEY OR ABEA Sec. 10-245-3	BLK. AND				
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.)		12. COUNTY OR PARISH		
		3528' DF		Lea	New Mexico	
16.	Check Ar	propriate Box To Indicate N	lature of Notice Report of	or Other Data		
	NOTICE OF INTEN			SEQUENT REPORT OF :		
TEST WATER S						
FRACTURE TRE		MULTIPLE COMPLETE	WATER SHUT-OFF FRACTURE TREATMENT	ALTERING C		
SHOOT OR ACL		ABANDON*	SHOOTING OR ACIDIZING	X ABANDONME		
REPAIR WELL		CHANGE PLANS	(Other)			
(Other) Convert to Water Injection X (Other) (Other) Convert to Water Injection X						
17. DESCRIBE PROP	OSED OR COMPLETED OPE ork. If well is direction	RATIONS (Clearly state all pertinen mally drilled, give subsurface loca:	t details, and give pertinent da	ates, including estimated dat	te of starting any	
mixed 3) Drilla 4) Resque 5) Resque and 50 6) Drilla 7) Cleana 8) Drilla 9) Set 13 10) Cement WOC 24 11) Drilla 12) Perfor with 4 shot 13) Treate 20/40 brine 14) Set 13 15 Lbreby certified	2% CaCl. WOO ed out cement eezed leaks at eezed leak int 0 sacks 50/50 ed out cement ed out 3465-35 ed new hole 35 3 joints (527' ted 4" OD casi 4 hours. ed out cement rated 4" OD ca 13 shots, 3577 ts, total of 4 ed perfs. 3530 sand, 200# be 10 joints (355	334-865'. 421' with 100 sacks erval with 100 sacks Class "H" Calcele. 360-421'. Pressure 31'. 31-3684'. ) 4" OD 13.34# R3 K- ng liner with 400 sa 3610-3622' PBTD. asing 3530-3542' with -3582' with 6 shots. -3602' with 1500 gal enzoic acid flakes ar 59') 2-3/8" OD tubing	S Class "H" cement S Class "C" cement, WOC 13 hours. tested leak interv 55 HyDril Ruff-Kot acks Class "C" ceme 13 shots, 3545-35 3593-3595' with 3 s. 15% NE acid, 80 ad 400# rock salt.	mixed 2% CaCl. V 25 sacks Class ' al to 500#, held e casing liner 32 ont mixed 6# salt 48' with 4 shots shots, and 3599-	WOC 48 hours. "H" cement okay. 145-3672'. per sack. , 3552-3564' -3602' with brine, 10,000#	
(Sign signed	ied) D. R. Crow	D. R. Crow TITLE I	lead Clerk	DATE9-7	7–76	
(This space fo	r Federal or State offi	ce use)				
APPROVED B CONDITIONS	Y OF APPROVAL, IF A	TITLE	ана —	ACCEPTED FOR RE	CORD	
				SEP 19 197	Ъ	
			1			
		Jee Instruction	s on Reverse Side	U. S. GEOLOGICAL S HOBBS, NEW ME		

-4

4

*4
- 1

## Myers Langlie-Mattix Unit Well No. 224 - Continued

15) Pump tested Langlie-Mattix perfs. 3530-3602' July 1-August 31, 1976, averaging 3.6 bbls. oil and 42 bbls. water per day.

Skelly proposes to continue its conversion program on this well as indicated on Sundry Notices and Reports on Wells Form 9-331 dated 10-24-75, steps No. 10, 11, and 12.

「神神」