Form 9-881 a		Approval expires 12-31-60.	
(Feb. 1951)	(SUBMIT IN TRIPLICATE)	Land Office Las Cruces 032450 (a)	
	UNITED STATES	Lease No.	
	DEPARTMENT OF THE INTERIOR	Unit	
	GEOLOGICAL SURVEY		
*			

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	
	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
	SUBSEQUENT REPORT OF ABANDONMENT
	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

South Nattix Unit		September 5,	19 61	
Well No. 2 is located	660 ft. f	rom_ $\begin{cases} \mathbf{N} \\ \mathbf{S} \\ \end{bmatrix}$ line a	and 1980 ft. from $\left\{ \begin{matrix} \mathbf{E} \\ \mathbf{W} \end{matrix} \right\}$ line of sec.	15
SE/4 SW/4 Sec. 15	1-24S,	()	NMPM	
(1/4 Sec. and Sec. No.) Fowler	(Twp.)	(Range)	(Meridian) Hew Mexico	
(Field)	(Coi	unty or Subdivision)	(State or Territory)	

The elevation of the derrick floor above sea level is <u>3274</u> ft. <u>3263 GL</u>

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

In accordance with Form 9-331a approved 9-5-61, remedial work done and results obtained are as follows:

Squeezed perforations 9950'-10, 048' with 300 sx cement. Drilled out to 9990', Sandriled perforations 9958-61'; 9968-71'; 9977-80'; and acidized with 4000 gallons 15%

Prior to workover, pumped 99 BO X 31 BW in 24 hrs. Gas TSTM after workover, pumped 192 BO X o W in 24 hrs. Gas TSTM.

I understand that	t this plan of work must receive approval in writing	g by the Geological Survey before operations may be commenced.
Company	Pan American Petroleum C	orporation
Address	Box 68	Original Signed by:
	Hobbs, New Mexico	V. E. STALEY By
		Title Area Supterintendent

GPO 862040