

Form 9-331
(May 1968)

UNITED STATES OFFICE OF THE SECRETARY OF THE INTERIOR
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
MAY 3 10 34 AM '68

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		5. LEASE DESIGNATION AND SERIAL NO. NM 037667
2. NAME OF OPERATOR Pan American Petroleum Corp.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR Box 68, Hobbs New Mexico		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 330' FSL x 1650' FEL, Sec. 9 (Unit O, SW 1/4 SE 1/4)		8. FARM OR LEASE NAME C. MYERS B Federal
14. PERMIT NO.		9. WELL NO. 24
15. ELEVATIONS (Show whether DF, RT, OR, etc.) 3284' R. D. B.		10. FIELD AND POOL, OR WILDCAT FOWLER BLINERY
		11. SEC., T., R., M., OR BLK., AND SURVEY OR AREA 9-24-37 NMPM
		12. COUNTY OR PARISH LEA
		13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☒	REPAIRING WELL ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACTURE TREATMENT ☒	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	
(Other) ☐			

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

In accordance w/ Form 9-331 submitted 4-18-66, well was fraced w/ 30,000 gal gelled brine containing 1 1/2" sand/gal and 3000# glass beads. Evaluated and restored to production.

Prior to W.O., pumped 8 BO x 3 BW in 24 hours. After W.O., pumped 107 BO x 72 BW in 24 hours.

TD- 7737 OC- 4-18-66
PBD- 7647 COMP: 4-27-66
4 1/2" CSA 7718'

PERFS: 5513-24, 40-60, 90-99, 5678-82, 5706-11, 31-35, 46-50, 54-69

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Area Supr

DATE

4-28-66

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

MAY 2 1966

*See Instructions on Reverse Side

J. L. GORDON
ACTING DISTRICT ENGINEER

04- USGS-H
1- NW
1- SW
FI
6