

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions
reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC- 032450 (6)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL ☒ GAS ☐
WELL WELL OTHER

2. NAME OF OPERATOR

Amoco Production Company

3. ADDRESS OF OPERATOR

BOX 68, HOBBS, N. M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1873.3' FSL x 2086.7' FWL Sec. 15 (Unit K, NE 1/4 SW 1/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3266' R. D. B.

7. UNIT AGREEMENT NAME

SOUTH MATTIX UNIT Fed.

8. FARM OR LEASE NAME

9. WELL NO.

21

10. FIELD AND POOL, OR WILDCAT

FOWLER ELLENBURGER

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

15-24-37 NMPM

12. COUNTY OR PARISH

LEA

13. STATE

N.M.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐MULTIPLE COMPLETION ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☒

(Other)

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☒(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

Tested casing & found leak @ 4792'. Cut &
Pulled casing from 4831'. Re-run 5 1/2" casing
& banded on stub @ 4831'. Tested w/ 1000 # PSI.
Test O.K. acidized perf 9790-9830 w/
1000 gal 15% NE. Evaluated and restored
to prod.
Prior - watered out.
after - Pmp 161 BO x 98W 24 Hrs.

TD-9849'

OC-4-19-74

5 1/2" CSA 9849'

Comp-6-3-74

Perfs: 9790-9830'

18. I hereby certify that the foregoing is true and correct

SIGNED

Roy R. Yakum

TITLE ADMINISTRATIVE ASSISTANT

DATE JUN 4 1974

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

JUN 5 1974

U.S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

*See Instructions on Reverse Side

4- USGS- Hobbs
1- DIV
1- SUSP
1- REY
1- NRCO
1- CONVO
1- JDTX
1- TENNCO