

UNITED STATES
DEPARTMENT OF THE INTERIOR

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved,
Budget Bureau No. 42-R1424.

GEOLOGICAL SURVEY

HUBBS OFFICE B. C. C.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to deepen or plug back to a different reservoir.
See APPLICATION FOR PERMIT—" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

NM-0321613

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

LC0324506

7. UNIT AGREEMENT NAME

SOUTH MATIX
UNIT FEDERAL

8. FARM OR LEASE NAME

9. WELL NO.

22

10. FIELD AND POOL, OR WILDCAT

FOWLER Blinbury

11. SEC. T., R., M., OR BLK. AND
SURVEY OR AREA

15-24-37 NMPM

12. COUNTY OR PARISH

Lea

13. STATE

N. M.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐ DRILLING

2. NAME OF OPERATOR

Pan American Petroleum Corp.

3. ADDRESS OF OPERATOR

Box 68 Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface
1930' FWLX 710' FNL, Sec. 15 (Unit C, NE 1/4 NW 1/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

Catus Drilling Co., spudded 11" hole, 11:00 A.M. 11-4-66.
Set 8 5/8" OD 24" J-55 Casing at 1014' w/ 375 sx 4% Hel and
100 sx Neat. Cement circulated. After 18 hours tested
casing w/ 1000 PSI for 30 minutes. Test O.K.. Reduced
hole to 7 7/8" at 1014' and resumed drilling.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Area Supt.

DATE

11-8-66

(This space for Federal or State office use)

APPROVED BY

TITLE

APPROVED

DATE

CONDITIONS OF APPROVAL, IF ANY:

NOV 14 1966

J L GORDON
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

4-USGS-12
1-MSU
1-SUPP
1-224
1-STATE LAND
1-ATLANTIC
1-COORO
1-STD. & TAY
1-ATLANTIC