

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPL
(Other instructions
verse side)TE
reForm approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-032450-B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☐ GAS WELL ☐ OTHER ☒ Drilling

2. NAME OF OPERATOR

Am American Petroleum Corp.

3. ADDRESS OF OPERATOR

Box 68 Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

910' FWL x 1980' FWL Sec. 15, (Unit C, NE/4 NW/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3261' RDB

7. UNIT AGREEMENT NAME

South Matrix Unit Fed.

8. FARM OR LEASE NAME

9. WELL NO.

25

10. FIELD AND POOL, OR WILDCAT

FOWLER ELLENBURGER

11. SEC., T., R., M., OR BLK. AND
SURVEY OR ALFA

15-34-37 NMPM

12. COUNTY OR PARISH

LEA

13. STATE

NM

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☒
☐
☐
☐

REPAIRING WELL

☐
☐
☐
☐

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

Spudding

☒(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Ord Arlq Co spudded 17 1/2" hole 4:30 PM 10-29-68.
On 10-31-68, 13 3/8" OD 48" H-40. Casing was set
@ 710' w/800 sq. neat. Cement Circ. After 70C
23 hours, tested casing w/1200 psi for 30 min.
Test O.K.

Reduced hole to 11" @ 710 and resumed
drilling operations.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

AREA SUPERINTENDENT

DATE

11-7-68

(This space for Federal or State office use)

APPROVED BY

TITLE

APPROVED

DATE

CONDITIONS OF APPROVAL, IF ANY:

NOV 11 1968

*See Instructions on Reverse Side

J L GORDON
ACTING DISTRICT ENGINEER

+4- USGS.H
1- NSW
1- SUSP
1- RRV
1- ATL
1- TENNECO
1- STD OF TOY
1- CONOCO
1- STATE LAND