

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE*
(Other Instructions on
reverse side)Form approved
Budget Bureau No. 42 R1424.

9. LEASE DESIGNATION AND SERIAL NO.

LC-032339 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
Continental Oil Company

3. ADDRESS OF OPERATOR
Box 460, HOBBS, N.M. 88240

4. LOCATION OF WELL (Specify location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
2080' FSL + 2080' FEL of Sec. 10

14. PERMIT NO.

15. ELEVATIONS (Show whether DE, RT, GR, etc.)
3245' GR

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
MATTIX

9. WELL NO.
2

10. FIELD AND POOL, OR WILDCAT
Fowler Devonian

11. SEC., T., R., M., OR BLM. AND
SURVEY OR AREA
Sec 10 T-24S R-37E

12. COUNTY OR PARISH
LEA

13. STATE
N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐Communication Repaired ☒(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

12-27-76 POOH w/rod + tbg. SIH w/RBP + pkr
12-28-76 GIH + set RBP at 7295' + pkr. at 3003'. Tested to 1000'
Dumped sand thru tbg. Loaded hole. Released + reset pkr. at
2404'. Perf. 2800'-02' w/2 JS PF. Established circulation
thru 7" - 9 5/8" annulus. Circulated thru casing annulus w/100 BTFW
Pumped 400 SX. Class "C" cmt., 2% CaCl. Displaced to 2720'.
12-31-76 No backflow. POOH w/plr. Ran temp. survey. TOC at 800'-900'.
GIH w/bit. Tagged cmt. at 2675'. DO to 2756'. Free to 2795'.
DO cmt. to 2805'. Tagged + DO cmt. to 2815'.
1-1-77 POOH w/bit. GIH + set pkr. at 2769'. Swabbed dry. No indication of
backflow.
1-4-77 Released pkr. + POOH. GIH + washed sand off RBP. Could not
retrieve RBP or pkr. Had to fish both. Pulled pkr. milled RBP +
pushed to bottom. POOH. Laid down workstring. Ran + set 2 3/8" tbg.
at 7404'. Prep. to test.

18. I hereby certify that the foregoing is true and correct

SIGNED

Wm. G. [Signature]

TITLE

Admin. Supr.

DATE

5-25-77

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

DATE

MAY 31 1977

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

*See Instructions on Reverse Side

USGS (5), NMFCU (4), 7/10

RECEIVED

JUN 7 1977

U.S. CONSERVATION COMM.
WASH, D. C.