| COPIES RECEIVED | | | Form C-103 | |
|--|--|-------------------------------------|-------------------------------------|-------------|
| TRIBUTION | | | Supersedes Old | |
| FE | NEW MEXICO OIL CONSERVATION COMMISSION | | C-102 and C-103 Effective 1-1-65 | |
| FILE | | | Ellective 1-1+65 | S |
| U.S.G.S. | 1 | | 5a. Indicate Type o | of Lease |
| LAND OFFICE | 1 | | State | Fee X |
| OPERATOR |] | 5. State Oil & Gas | | |
| | - | | | |
| (DO NOT USE THIS FORM FOR PRI USE "APPLICAT | RY NOTICES AND REPORTS ON WELL OPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A TION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOS | S Different reservoir. Sals.) | | |
| 1 | | | 7. Unit Agreement | Name |
| VIELL X GAS WELL | OTHER. | | | |
| 2. Name of Operator | | | 8. Farm or Lease 1 | lame |
| John Yuronka | | | Hodges | |
| 3, Address of Operator | | | 9. Well No. | |
| 122-C Central Builds | ing, Midland, Texas 79701 | | | |
| 4. Location of Well | <u>,</u> | | 10. Field and Pool | or Wildest |
| UNIT LETTER P 44 | 9 FEET FROM THE South LINE | AND FEET FROM | | |
| THE EAST LINE, SECTION | ON 8 TOWNSHIP 24-S | ange <u>37-E</u> nmpm. | | |
| | 15. Elevation (Show whether DF, RT, | GR, etc.) | 12. County | |
| | 3277' DF | | Lea | |
| Check . | Appropriate Box To Indicate Nature | of Notice, Report or Oth | ier Data | |
| NOTICE OF IN | TENTION TO: | SUBSEQUENT | REPORT OF: | |
| | | | | |
| PERFORM REMEDIAL WORK | PLUG AND ABANDON REMED | IAL WORK | ALTERIN | G CASING |
| TEMPORARILY ABANDON | | TEST AND CEMENT JOB | PLUG AND | ABANDONMENT |
| | отн | ER | | |
| OTHER | | | | |
| | | | | |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1903.

Total Denth 3470'.

Ran 93 its. - 3641' - of /-1/2" 10.5# J-55 S.T.&C. casing and set at TD. Cemented w/400 sacks Class "C" 50-50 Poznex "A" 2% Gel, 8# of salt per sack and 0.5% CFR-2. Cement calculated from a caliner log from TD to 2500', the base of the salt, and 100% excess was added. /1' of cement left in the pipe. Plug down at 3:15 p.m. on 10-10-75. Tested casing and cement w/1000# for 30 minutes after 18 hours and held OK.

| 18. I hereby certify | that the information above is true and o | omplete to the best of my knowledge and bel | lef. |
|----------------------|--|---|-----------------|
| SIGNED | no Colombar | TITLE Authorized Ager | 2t PATE10-13-75 |
| | | | |
| APPROVED BY | | | |
| CONDITIONS OF AF | PPROVAL, IF ANY: | TITLE | DATE |