

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other instructions on reverse side)Form approved.  
Budget Bureau No. 42-R1424.  
LEASE DESIGNATION AND SERIAL NO.

NM-0321613

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
2. NAME OF OPERATOR Amoco Production Company		7. UNIT AGREEMENT NAME South Mattix Unit	
3. ADDRESS OF OPERATOR P. O. Drawer A, Levelland, Texas 79336		8. FARM OR LEASE NAME South Mattix Unit	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface  330' FSL x 330' FEL, Sec. 15 (SE/4 SE/4 Unit P)		9. WELL NO. 30	
14. PERMIT NO.		10. FIELD AND POOL, OR WILDCAT Fowler Upper Yeso	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3227.1 GR		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 15-24-37	
		12. COUNTY OR PARISH Lea	
		13. STATE NM	

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON\* ☐CHANGE PLANS ☐

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT\* ☐Spud ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

## 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

On 11-26-77, Hillin Drilling Co. (Rig #3) spudded a 12½" hole at 2:00 a.m. Drilled to TD of 1066' and set 8-5/8" casing at 1066'. Cement with 500 sx cement with additives. Plugged down 3:30 a.m. 11-28-77. Circulated 100 sx WOC 19½ hours. Test casing with 1000# for 30 minutes. Test ok. Reduced hole to 7-7/8" and resumed drilling.

## 18. I hereby certify that the foregoing is true and correct

SIGNED

*Randy Atkins*

TITLE Staff Assistant (SG)

DATE 12-7-77

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

0 &amp; 4-USGS-Art

1-Div.

1-RC

1-Conoco

1-Chevron

1-Tenneco

1-Arco

1-Susp.

\*See Instructions on Reverse Side

ACCEPTED FOR RECORD

DEC 12 1977

U. S. GEOLOGICAL SURVEY  
HOBBBS, NEW MEXICO