

Form 9-331  
Dec. 1973Form Approved.  
Budget Bureau No. 42-R1424

**UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY**

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other ☐
2. NAME OF OPERATOR  
Amoco Production Co.
3. ADDRESS OF OPERATOR  
P. O. Box 68 Hobbs, NM 88240
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 750' FNL x 700' FEL, Sec. 15  
AT SURFACE: (Unit A, NE/4 NE/4)  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

## REQUEST FOR APPROVAL TO:

- TEST WATER SHUT-OFF ☐
- FRACTURE TREAT ☐
- SHOOT OR ACIDIZE ☐
- REPAIR WELL ☐
- PULL OR ALTER CASING ☐
- MULTIPLE COMPLETE ☐
- CHANGE ZONES ☐
- ABANDON\* ☐
- (other) ☐

## SUBSEQUENT REPORT OF:

- ☒
- ☐
- ☐
- ☐
- ☐
- ☐
- ☐
- ☐

**RECEIVED**  
FEB 28 1980  
U. S. GEOLOGICAL SURVEY  
HOBBS, NEW MEXICO

5. LEASE  
NM - 032 1613
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME  
South Mattix Unit Fed
8. FARM OR LEASE NAME  
South Mattix Unit Fed
9. WELL NO.  
38 Y
10. FIELD OR WILDCAT NAME  
Fowler Drinkard
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
15-24-37
12. COUNTY OR PARISH  
Lea
13. STATE  
NM
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)  
3246.3

(Do not report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

On 2-2-80 Verna Drilling Co. (Rig #12) spudded a 12-1/2" hole at 3:00 PM. Drilled to a TD of 1068' and ran 9-5/8" casing set at 1068'. Cemented with 400 sx Class C cement with 3% Sodium Silicate and 6# salt/sx and 1/4# sulophane 1 sx and 150 sx Class C cement with 2% CACL. Plugged down 4:45 PM 2-5-80. Circulated 90 sx. WOC 18 hrs. Tested casing with 1000# for 30 min. Test OK. Reduced hole to 8-3/4" and resumed drilling.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Bob Davis TITLE Assist. Admin. Asst. DATE 2-25-80

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

0+4 USGS-H, 1-Hou, 1-Susp, 1-BD, 1-ARCO

\*See Instructions on Reverse Side

