Form 9-331 Dec. 1973

Form Approved. Budget Bureau No. 42-R1424

UNITED STATES	5. LEASE NM-7488
DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME Myers Langlie Mattix Unit 8. FARM OR LEASE NAME
1. oil gas well other Water Injection Well 2. NAME OF OPERATOR	Myers Langlie Mattix Unit 9. WELL NO. 183
Getty Oil Company 3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME Langlie Mattix 11. SEC., T., R., M., OR BLK. AND SURVEY OR
P. O. Box 730, Hobbs, New Mexico 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) Unit 1tr. O, 660 FSL & 1980 FEL	AREA Sec. 4 T24-S R37-E 12. COUNTY OR PARISH 13. STATE
AT SURFACE: AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	Lea New Mexico 14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 3284 G.L.
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) Casing Connections U.S. GEOLOGICAL SURVE HOBBS, NEW MEXICO 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and rooks pertinent to this work.)*	
measured and true vertical depths for all markers and zones pertinent to this work.)* Riser on 8 5/8" OD and 5 1/2" OD casing brought to surface.	
Inspected by Tony Plattsmier of the NMOCD on	2/4/81.
	_
Subsurface Safety Valve: Manu. and Type	
APPROVED BY TITLE T	ACCEPTED FOR RECORD
*See Instructions on Revers	U.S. GEOLOGICAL SURVEY ROSWELL, NEW MEXICO