

P. O. BOX 1980

11-WIOS HOBBS, NEW MEXICO 88240

1-BWI-Foreman

6-USGS-Roswell

1-JDM-Engr.

1-File

Form 9-331  
Dec. 1973

Form Approved.

Budget Bureau No. 42-R1424

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other
- 
2. NAME OF OPERATOR  
Getty Oil Company
- 
3. ADDRESS OF OPERATOR  
P.O. Box 730, Hobbs, NM 88240
- 
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: Unit Ltr. J, 1980' FSL & 1980' FEL  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:
- 
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

- |  |                 |
|--|-----------------|
| 5. LEASE<br>NM-7488  |                 |
| 6. IF INDIAN, ALLOTTEE OR TRIBE NAME                                     |                 |
| 7. UNIT AGREEMENT NAME<br>Myers Langlie Mattix Unit                      |                 |
| 8. FARM OR LEASE NAME<br>Myers Langlie Mattix Unit                       |                 |
| 9. WELL NO.<br>164   |                 |
| 10. FIELD OR WILDCAT NAME<br>Langlie Mattix                              |                 |
| 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA<br>Sec. 4, T-24S, R-37E |                 |
| 12. COUNTY OR PARISH<br>Lea  | 13. STATE<br>NM |
| 14. API NO.  |                 |
| 15. ELEVATIONS (SHOW DF, KDB, AND WD)<br>3278.4' GR                      |                 |

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>
(other)	<input type="checkbox"/>

SUBSEQUENT REPORT OF:

X

DECEIVE

SEP 14 1981 (NOTE: Ret John)

OIL & GAS  
U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

8/31/81 Drilled 7 7/8" hole to 3769'. Ran 93 jts. (3740') 5 1/2" OD 14# K-55 ST&C casing and set at 3752'. Western cemented w/820 sxs. Lite, 18% salt, and 1/4# flocele. Tailed in w/250 sxs. 50/50 Poz Mix and 1/4# flocele. Total cement - 1070 sxs. Circulated 100 sxs. cement. WOC. Released rig.

Subsurface Safety Valve: Manu. and Type

Set @ 500 Ft.

18. I hereby certify that the foregoing is true and correct

ACCEPTED FOR RECORD  
SIGNED ROGER A. CHAPMAN  
Date BY: CHAPMAN

TITLE Area Superintendent DATE 9/10/81

(This space for Federal or State office use)

APPROVED BY SEP 18 1981  
CONDITIONS OF APPROVAL, IF ANY:

U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO

\*See Instructions on Reverse Side