

O+5 - USGS - Roswell
1 - I - MLMU - Jal
1 - Admin. Unit - Midland

11 - WIO's

1 - Fi

Form Approved.
Budget Bureau No. 42-R1424M. M. OIL CONS. COMMISSION
P. O. BOX 1980
HOBBS, NEW MEXICO 88240UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

RECEIVED
AUG 17 19811. oil ☒ gas ☐ other ☐2. NAME OF OPERATOR
Getty Oil CompanyOIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO3. ADDRESS OF OPERATOR
P. O. Box 730, Hobbs, New Mexico 882404. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: Ltr. N, 660' FSL & 1980' FWL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐

SUBSEQUENT REPORT OF:

☒
☐
☐
☐
☐
☐
☐
☐
☐
(other) Commence Drilling Operations5. LEASE
NM-7488
6. IF INDIAN, ALLOTTEE OR TRIBE NAME7. UNIT AGREEMENT NAME
Myers Langlie Mattix Unit8. FARM OR LEASE NAME
Myers Langlie Mattix Unit9. WELL NO.
18210. FIELD OR WILDCAT NAME
Langlie Mattix11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 4, T-24S, R-37E12. COUNTY OR PARISH
Lea13. STATE
NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3266.4 GRRECEIVED
AUG 25 1981
U.S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

(Note: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

8/8/81 Marc Drilling Co. moved in and rigged up. Spudded 12 1/4" hole. Drilled 12 1/4" hole to 505'. Ran 12 jts. (492') 8 5/8" 24# K-55 & set at 504'. Dowell cemented with 135 sxs Lite, 1/4# Flocele, 2% CaCl & 175 sxs. Class "C" cement with 2% CaCl. Total cement 210 sxs. Circulated 100 sxs. cement.

8/9/81 WOC 18 hrs. Pressured up on casing to 1200# for 30 min. OK.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

Date 8/11/81
ACCEPTED FOR RECORD
ROGER A. CHAPMAN

TITLE Area Superintendent DATE 8/11/81

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

AUG 24 1981

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side

RECEIVED
AUG 25 1981
OIL CONSERVATION DIV.

RECEIVED

AUG 25 1981

OIL CONSERVATION DIV.