

N. M. OIL CONS. COMMISSION  
P. O. BOX 1980  
HOBBS, NEW MEXICO 88240

Form 9-331  
Dec. 1973

Form Approved.  
Budget Bureau No. 42-R1424

0+5-MMS-Roswell

1-File

1-Engr. JDM

1-JA

1-Foreman BI

1-Laura

Midland

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐ other ☐

2. NAME OF OPERATOR  
Getty Oil Company

3. ADDRESS OF OPERATOR  
P.O. Box 730, Hobbs, New Mexico 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: Unit Ltr. P 660' FSL & 660' FEL  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON\* ☐

(other) Casing Connection

☐

☐

☐

☐

☐

☐

☐

☐

☐

☒

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Riser on 8 5/8" OD and 5 1/2" OD casing brought to surface.

Riser on and casing brought to surface.

Riser on and casing brought to surface.

Inspected by Ron Castleberry on

Inspected by Nathan E. Clegg on

Inspected by Tony Plattsmier on

Inspected by E.W. Seay on 9/28/82

Inspected by Otto Wink on

Subsurface Safety Valve: Manu. and Type

Set @ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Peter W. Chester TITLE Area Superintendent

September 29, 1982

PETER W. CHESTER

APPROVED BY  
CONDITIONS OF APPROVAL IF ANY:

TITLE DATE

SEP 29 1983