INCLINATION REPORT

		1110211111111	DR IVE: OK!	
OPERATOR: DOYLE HARTMAN		ADDRESS: P.O. BOX 10426, MIDLAND, TEXAS 79702		
LEASE NAME	: E.E. JACK	WELL NO: #5	FIELD:	
LOCATION:_	SECTION 8, T24S, R37	E LEA CO., N.M.		
DEPTH	ANGLE INCLINATIO	N DEGREES DISPLAC	DISPLACEMENT CEMENT ACCUMULATED	
402	1/2	. 87	3.4974	
929	1 1/2	2.62	17.3048	
1356	1 1/4	2.18	26.6134	
1830	2	3.49	43.1560	
2262	2	3.49	58.2328	
2449	2 1/4	3.93	65.5819	
2925	3 1/2	6.10	94.6179	
3500	3	6.10	124.6904	
			CACTUS DRILLING COMPA	
AFFIDAVIT: BEFORE ME,	THE UNDERSIGNED AUTH	ORITY, APPEARED RENE	<u>E HILL</u> KNOWN TO ME TO BE T	THE PERSON WHOSE NAME
IS SUBSCRI	BED HEREBELOW, WHO, O	N MAKING DESPOSTION.	UNDER OATH STATES THAT SH , AND THAT TO THE BEST OF	IE IS ACTING FOR AND IN
BELIEF SUC	H WELL WAS NOT INTENT	IONALLY DEVIATED FRO	M THE TRUE VERTICAL WHATSO	EVER.
			Lexi Lill AFFIANT'S SIGNATURE	
SWORN AND	SUBSCRIBED TO IN MY	RESENCE ON THIS THE	JUST DAY OF OCT.	, 1985
			Jul R. Tay	1
			NOTARY PUBLIC IN AND	FOR THE COUNTY

SEAL

OF MIDLAND, STATE OF TEXAS

Notary Public, State of Texas My Commission Expires: 7-5-89

GARLIN R. TAYLOR

Motorby Construction (1997)

Better when the Construction (1997)

State when the Mark Construction (1997)

RECEIVED

OCT 22 1985

OCT 25 1985
