

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-30618
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Liberty Royalties
8. Well No. 6
9. Pool name or Wildcat Jalmat (Gas)
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3305 G.L.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator
Doyle Hartman

3. Address of Operator
Post Office Box 10426, Midland, Texas 79702

4. Well Location
Unit Letter 0 : 660 Feet From The South Line and 1400 Feet From The East Line

Section 7 Township 24-South Range 37-East NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☒
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Drilled well to a total depth of 3486' RKB. Ran 107 joints of 7" OD, 23 lb/ft., ST&C, and LT&C casing and landed at 3486' RKB. Cemented casing with 750 sacks of API Class-C cement containing 3% Halliburton Econolite, 5 lb/sx Gilsonite and 1/2 lb/sx Flocele, followed by 350 sacks of a 50-50 blend of API Class-C cement and Pozmix A containing 2% gel, 18% salt and 1/4 lb/sx Flocele. Plug down at 3:05 AM CDT 8-26-89. Pressure tested to 2000 psi and pressure held okay. Released pressure and float held okay. Circulated 105 sacks of excess cement to pit.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Michelle Wilcox TITLE Administrative Assistant DATE 8-30-89

TYPE OR PRINT NAME Michelle Wilcox

TELEPHONE NO. 915/684-4011

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

SEP 6 1989

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: