



Amoco Production Company

October 27, 1992

State of New Mexico
Oil Conservation Division
P.O. Box 1980
Hobbs, New Mexico

Attn: Jerry Sexton, Supervisor - District 1

File: KWB-WF

Gentlemen:

Pressure Test Chart
South Mattix Federal Unit Well Nos. 42, 43, & 44
Fowler Upper Yeso Pool
Sec. 15, T-24S, R-37E
Lea County, New Mexico

Reference your letter of October 7, 1992, requesting pressure test charts on subject wells. On October 14, 1992, we advised your office that the charts for these wells had been lost and it would be necessary for us to re-test the wells.

Attached for your files are the original charts which are the results of our re-test. The wells were tested according to NMOCD standards and no leaks were detected.

If additional information is required, please contact Howard Black at (713) 584-7213.

Yours very truly,

K. W. Brand HB

K.W. Brand
Administrative Services Manager

KWB/ksb
attachments